

## VALID INFOTAINMENT SYSTEM V0.6.22 RELEASE NOTES

## Introduction

This document contains information about the Valid Infotainment System revision history, as well as outstanding identified issues with interim solutions.

## **Revision History**

Revision	Issue Resolved / Feature Added
v06.22	VNC and Sygic software has been updated:
	<ul> <li>GPS position loss has been corrected</li> </ul>
	<ul> <li>New navigation features have been added, including lane departure pop-up and improvements to preference list and route planning</li> </ul>
	<ul> <li>Audible navigation prompts have been improved</li> </ul>
	<ul> <li>Issues with audio source selection on the passenger touchscreen have been fixed</li> </ul>
	<ul> <li>Audio volume now returns to the previous level and source after a call is ended or declined</li> </ul>
	<ul> <li>VNC module firmware can now be updated from the infotainment screen</li> </ul>
	Stability issues have been fixed:
	<ul> <li>Main and overhead displays should now freeze less or not at all</li> </ul>
	<ul> <li>Bluetooth® performance should be improved when source is unexpectedly disconnected</li> </ul>
	Improved audio reset routine prevents unwanted audible pop sound on reboot
	The network menu display of the Sygic software version has been corrected
	<ul> <li>The SiriusXM® parental lock icon has been resized</li> </ul>
v0.6.10	<ul> <li>If the audio is set to a source other than Bluetooth®, any navigation prompts will temporarily mute the audio so the prompts can be heard.</li> </ul>
	<ul> <li>Echo cancellation source during phone calls has been fixed.</li> </ul>
	<ul> <li>Volume level is saved during a phone call and restored to that level on the next cal</li> </ul>
	Bluetooth® auto reconnect has been improved.

VDC01087 REV D OCT 2024 PAGE 1 OF 3

VALID INFOTAINMENT SYSTEM OPERATION MANUAL

Revision	Issue Resolved / Feature Added
v0.6.9	Sygic software update is now available through the network device list in the settings menu (Settings > Settings > System Information).
	Bluetooth® functionality improvements have been made:
	Stability improved upon device removal.
	For large contact lists:
	<ul> <li>Stability has been improved.</li> </ul>
	Scroll bar added .
	Video lag has been reduced.
	<ul> <li>Leveling display improvements have been made:</li> </ul>
	<ul> <li>Bubble display has been fixed.</li> </ul>
	<ul> <li>Passenger touchscreen firmware has been updated.</li> </ul>
	<ul> <li>Ride height button has been fixed on dual hydraulic and air suspension systems.</li> </ul>
	<ul> <li>SiriusXM can now be chosen as a source only when available.</li> </ul>
	<ul> <li>Status display of accent light has been fixed.</li> </ul>
	<ul> <li>Video feed has been stabilized when the vehicle is being started.</li> </ul>

VDC01087 REV D OCT 2024 PAGE 2 OF 3

OPERATION MANUAL

## **Known Issues**

The table below lists conditions that may be encountered even after the Valid Infotainment System firmware is updated to version 0.6.22, as well as possible solutions.

Issue	Interim Fix
Bluetooth® audio controls from phone for Valid Infotainment System audio do not function.	No interim fix available at this time.
No camera feed on either the Valid Instrument Cluster or the Valid Infotainment screen.	HDMI-to-IP Encoder must be reset.
GPS navigation does not start.	Double-tap the Sygic icon to launch the app.
Camera view does not change with signal light (Anthem / Cornerstone).	The Delta Mobile camera controller must be updated.

VDC01087 REV D OCT 2024 PAGE 3 OF 3