



VALID INFOTAINMENT SYSTEM

MY2025 V0.0.37 RELEASE NOTES

Introduction

This document provides information about the Valid Infotainment System revision history for model year 2025, as well as outstanding identified issues with interim solutions.

Revision History

Revision	Issue Resolved / Feature Added
v0.0.37	- The memory management on the cab interface module has been improved to prevent system lockup. - The alignment of the level bubble on the leveling screen has been adjusted.
v0.0.35	- In full-screen camera view, Valid Infotainment display no longer freezes upon reactivation from sleep state. - Improved Ethernet network stability after a cold start. - Fuse detection has been added, with alerts displayed for blown fuses. - Sygic software has been updated to improve calculations for long-distance route planning. - Leveling messaging improved - status is now displayed properly when leveling process is complete.

Known Issues

The table below lists conditions that may be encountered even after the Valid Infotainment System firmware is updated to v0.0.37, as well as possible solutions.

Issue	Interim Fix
Bluetooth® audio controls from phone for Valid Infotainment System audio do not function.	No interim fix available at this time.
No camera feed on either the Valid Instrument Cluster or the Valid Infotainment screen.	HDMI-to-IP Encoder must be reset.
GPS navigation does not start.	Double-tap the Sygic icon to launch the app.
Camera view does not change with signal light (Anthem / Cornerstone).	The Delta Mobile camera controller must be updated.